

SITE NAME: ANWILKA

LANDSCAPE UNIT NUMBER: C19
LANDSCAPE UNIT GRADE: Grade II


ADDRESS OF THE SITE

PROPERTY NO 152
 SITE ADDRESS Raithby-Annandale Road
 CURRENT USE Agricultural werf
 ORIGINAL USE Agricultural werf

PROTECTION AND GRADING

Curr.NHRA Protection S34
 >60YRS? **Yes**
 PROPOSED GRADING Grade IIIc

MAP



SIGNIFICANCE

Associational	Low	Representivity	Medium
Age	Low	Rarity	Low
Scientific	None	Archaeology	
Symbolic	Low	Intangible	
Architectural	Low		

ARCHITECTURAL STYLE

Cape Revival

ARCHITECT/BUILDER

LATITUDE/LONGITUDE

-34.01908 18.8019733333

SITE DESCRIPTION

This house, although much altered, has at its core an early 20th century Cape Revival layout, and has landmark significance due to its location on a gentle rise within the valley, facing north. A "werf wall" and structured landscaping create a clear werf space.

STATEMENT OF SIGNIFICANCE

This house, although much altered, has at its bones a Cape Dutch Revival layout, and has landmark significance due to its location on a rise, facing north. It has some limited architectural interest, as well as landmark, scenic and contextual significance.

INTERIOR DESCRIPTION

GROUPING WITH OTHER SITES

EVIDENCE OF DEMOLITION

SITE HISTORY

LANDSCAPE SIGNIFICANCE

Mature trees surround the house and avenue approach.

CONTEXTUAL DESIGN

This building represents a later, more modest Cape Dutch Revival layer of buildings within the Eerste River Valley.

INVASIVE ELEMENTS

HERITAGE VULNERABILITY